

MULTITHRESHOLD MEASUREMENT AND ANALYSIS OF PULSED LASER DAMAGE ON OPTICAL SURFACES

by

J. O. Porteus, J. L. Jernigan, and W. N. Faith Physics Division, Michelson Laboratories Naval Weapons Center, China Lake, CA 93555

Presented at the Ninth Boulder Damage Symposium, Materials for High Power Lasers
4-6 October 1977, Boulder, Colorado
(to be published in Proceedings)

AD NO.

December 1977

Research Sponsored by the Office of Naval Research

under

Task Number RR0220202

DDC

DECEMBER

MAR 13 1978

MEGETTE

B

Approved for Public Release; Distribution Unlimited

Reproduction in whole or in part is permitted for any purpose of the United States Government

ONR Technical Report No. 2

MULTITHRESHOLD MEASUREMENT AND ANALYSIS OF PULSED LASER DAMAGE ON OPTICAL SURFACES

by

J. O. Porteus. J. L. Jernigan, and W. N. Faith Physics Divisio., Michelson Laboratories Naval Weapons Center, China Lake, CA 93555

Presented at the Ninth Boulder Damage Symposium, Materials for High Power Lasers
4-6 October 1977, Boulder, Colorado
(to be published in Proceedings)

The second secon

December 1977

Research Sponsored by the Office of Naval Research

under

Task Number RR0220202




Approved for Public Release; Distribution Unlimited

Reproduction in whole or in part is permitted for any purpose of the United States Government

	((14)
UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE	E (When Date Entered)	TNWC-TR-JONR
REPORT DOCUME	NTATION PAGE	BEFORE COMPLETING FORM
1. REPORT NUMBER Technical Report No. 2V	A. GOVT.AGEESS	ON NOT 9 RECIPIENT'S CATALOG NUMBER
MULTITHRESHOLD MEASUREME POLSED LASER DAMAGE ON	ENT AND ANALYSIS OF SURFACES	Type of REPORT & PERIOD COVERED Technical Report
J. O. Porteus, J. L. Jer	nigan W. N./Fai	ith 8. CONTAACT OR GRANT NUMBER(*)
9. PERFORMING ORGANIZATION NAME A Naval Weapons Center China Lake, CA 93555	ND ADDRESS	Task No. RRØ22Ø2Ø2
11. CONTROLLING OFFICE NAME AND AI Office of Naval Research Metallurgy Branch Arlington, VA 22217	(Code 471)	Dec 77 13. NUMBER OF PAGE 19 1 TOPORT) DIFFICO 18. SECURITY CLASS (1) 11 TOPORT)
16. DISTRIBUTION STATEMENT (of this R		UNCLASSIFIED 154. DECLASSIFICATION/DOWNGRADING SCHEDULE
Approved for public mele	ase; distribution un	nlimited
17. DISTRIBUTION STATEMENT (of the about 18. SUPPLEMENTARY NOTES To be published in Proces	edings of the Ninth	Boulder Damage Symposium.
Materials for High Power	Lasers, 4-6 October	1977, Boulder, Colorado
Damage thresholds Failure modes Laser-optical components Mo mirrors	Optical coatings Pitting	Surface characterizati Surface uniformity Threshold estimation
20. ABSTRACT (Continue on reverse side if	necessary and identify by block n	number)
See back of form.		
	403019	
	and the second s	

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

The methodology of multithreshold analysis, a new approach to laser-damage research, is described. The comparison of thresholds for various damage-related effects identifies dominant failure mechanisms and provides better guidance for laser-materials technology. After a brief description of apparatus, the procedure for routinely measuring up to eight different thresholds per sample is given. The maximum-likelihood principle is used to derive an algorithm for computing thresholds and standard deviations. The use of a standard gold sample to verify reproducibility and to maintain long-term calibration is discussed. Examples of multithreshold results on uncoated and coated infrared optical components are presented. The following are some of the effects for which thresholds are compared: slip, roughening, cracking, pits, melting, craters, delamination of coatings, ion and light emission, and work function change.



MULTITHRESHOLD MEASUREMENT AND ANALYSIS OF PULSED LASER DAMAGE ON OPTICAL SURFACES

J. O. Porleus, J. L. Jernigan, and W. N. Faith Physics Division, Michelson Laboratories Nava: Weapons Center, China Lake, California 93555

ţ

The state of the s

The methodology of multithreshold analysis, a new approach to laser-damage research, is described. The comparison of thresholds for various damage-related effects identifies dominant failure mechanisms and provides better guidance for laser-materials technology. After a brief description of apparatus, the procedure for routinely measuring up to eight different thresholds per sample is given. The maximum-likelihood principle is used to derive an algorithm for computing thresholds and standard deviations. The use of a standard gold sample to verify reproducibility and to maintain long-term calibration is discussed. Examples of multithreshold results on uncoated and coated infrared optical components are presented. The following are some of the effects for which thresholds are compared: slip, roughening, cracking, pits, melting, craters, delamination of coatings, ion and right emission, and work function change.

Key words: Damage threshold; failure modes; laser-optical components; Mo mirrors; optical coatings; pitting; ripples; standard sample Au mirrors; surface characterization; surface uniformity; threshold estimation; windows.

1. Introduction

The damage resistance of optics for lasers may be improved with an understanding of important damage mechanisms and their relationship to material characteristics. The comparison of thresholds for the various observable damage-related effects provides a good basis for this understanding. Some of the effects typical of a bare metal mirror may be seen in figure 1. Slip bands and intergranular slip indicate susceptibility to stress damage, which can be related to yield strength, as shown in a companion paper [1]1. Melting, which produces the dark area in the dark-field micrograph, is an indicator of optical absorption. Laser-induced pitting, which occurs mainly on grain boundaries in figure 1, can be caused by segregated impurities. Cratering, identified by a raised rim around the melt zone, is usually caused by pressure associated with vaporization. Other effects measured by other techniques may also be informative. A change in surface work function, for example, can signal changes in surface composition or topography. Ion and light emission indicates plasma formation.

The present work presents the methodology of obtaining thresholds routinely and accurately for as many as eight different laser-induced surface effects, after a brief description of the apparatus, details of which are given elsewhere [2], the procedure for acquiring and reducing the data is discussed. The derivation of an algorithm based on the maximum-likelihood principle, which is used to compute thresholds and standard deviations, is also given. We then discuss the use of a standard gold sample to verify reproducibility and to maintain calibration. Finally, we present typical results and their interpretation on various infrared optical components.

2. Apparatus

Measurements are made in a previously described laser damage facility [2], where comprehensive target monitoring and careful beam characterization are key features. Our ultrahioh vacuum (UHV) test chamber was equipped with the following monitoring apparatus for the results presented here: (1) 20-power microscope; (2) Faraday cup with grounded entrance grid (10-ma/sr detection sensitivity at 35° off the laser beam axis) for sensing of target-emitted ions and neutrals having sufficient energy to produce secondary electrons; (3) an Auger analyzer with electron imager [2]. The electron images are generated by work function variations \geq 0.1 eV over the target surface caused by variations in surface composition and topography.

Figure 2 illustrates the Gaussian spatial intensity distribution of the 10.6 µm laser beam when focussed on the target by a ZnSe lens having a focal length of 24 cm. Temporally, each pulse consists of a train of mode-locked spikes which form an envelope of 100 nsec nominal duration. Inresholds given are peak thresholds, i.e., they refer to the time-integrated fluence of the damaging pulse at the point of maximum spatial intensity.

^{*} Work supported by the Naval Air Systems Command, the Office of Naval Research and NWC Independent Research Funds.

^{1.} Figures in brackets indicate the literature references at the end of this paper.

The data reduction equipment consists of a Hewlett-Packard Model 9821 calculator interfaced with a Tektronix Model 4662 interactive digital plotter. Data reduction is performed entirely in the calculator, while the plotter is used only for display of final results.

3. Experimental Procedure

The sample is exposed to one pulse at each of approximately 50 sites spaced at 1-mm intervals along its surface. Pulse energies, which are measured for each pulse [2], are uniformly distributed over a range which includes the thresholds for each of the damage effects of interest. The occurrence of light emission (flash) and pit formation are noted by an observer as they occur, while damage features which are more difficult to identify, e.g., slip, melting and cratering, are categorized with the aid of more sophisticated optical microscopy after the sample has been removed from the test chamber (fig. 1). The damage observed at each site is summarized by a set of code numbers, each number representing a specific effect. The data is reduced by entering the damage summary and corresponding peak energy fluence for each site into the calculator and applying the algorithm derived below.

3.1 Threshold Algorithm

The routine determination of up to eight thresholds per sample tested requires an algorithm permitting rapid data reduction. On the other hand, effective use of available data is important, since the fluence range of thresholds is often wide, and therefore incompatible with a high density of data prants. In this section we develop an algorithm which yields reproducible results with a minimum of computational complexity.

Consider the probability P_i of obtaining a certain type of damage X_i times out of N_i shots on fresh sites (1-on-1 damage) [3,4], all at the same fluence ϕ_i . This is represented by the binomial distribution

$$P_{i}(X_{i}; N_{i}; p_{i}) = {N_{i} \choose X_{i}} P_{i}^{X_{i}} (1 - p_{i})^{N_{i}-X_{i}},$$
 (1)

where

The second of the second of

$$P_{\underline{i}} = P_{\underline{i}}(\phi_{\underline{i}}, \phi, \sigma) \quad , \tag{2}$$

the probability of single-shot damage is a function of the damage threshold ϕ and its standard deviation σ , in addition to the fluence ϕ_1 . The problem is to obtain statistical estimators for ϕ and σ in terms of the damage data X_1 , N_1 and ϕ_1 . Our solution is based on the method of maximum-likelihood [5]. Maximizing the logarithm of the likelihood with respect to the parameters ε = ϕ or σ , leads to two expressions of the form

$$\frac{1}{2} \frac{\partial \mathbf{c}}{\partial \mathbf{r}} \left[\frac{\mathbf{r}_{\mathbf{i}} \left(\mathbf{1} - \mathbf{r}_{\mathbf{i}} \right)}{\mathbf{r}_{\mathbf{i}} \left(\mathbf{r}_{\mathbf{i}} \right)} \right] = 0 \quad .$$

Solving simultaneously for ϕ and σ yields the corresponding maximum likelihood estimators $\hat{\phi}$ and $\hat{\sigma}$. However, the functional form of p_1 is required. For computational simplicity we assume that p_1 is uniformly distributed, i.e.,

$$p_{1} = \begin{cases} 0 & ; & u_{1} \leq -\frac{1}{2} \\ u_{1} + \frac{1}{2} ; & |u_{1}| < \frac{1}{2} \\ 1 & ; & u_{1} \geq \frac{1}{2} \end{cases}$$
 (4)

where

$$u_1 = \frac{z_1 - \phi}{2\sqrt{3}} \quad . \tag{5}$$

Substituting eq. (4) in eq. (3), one finds that only those terms j for which $|u_j| < 1/2$ are nonzero. To further simplify the computation we neglect u_1^{-2} terms in the denominators, which are of the form $1/4 - u_1^{-2}$. As a result, our estimators differ from the true maximum-likelihood estimators in that data points near $u_1 = 1/2$ are less heavily weighted relative to those near $u_1 = 0$. This compensates to some degree for the fact that the distribution given by eq. (4) generally represents the sample distribution less accurately near $u_1 = 1/2$. Introducing eq. (5) and solving for ϕ yields

 $\hat{\phi} \simeq \frac{\left[\sum_{j=1}^{4} N_{j}\right] \left[\sum_{j=1}^{4} (X_{j} - \frac{1}{2}N_{j})\right] - \left[\sum_{j=1}^{4} N_{j}\right] \left[\sum_{j=1}^{4} (X_{j} - \frac{1}{2}N_{j})\right]}{\left[\sum_{j=1}^{4} N_{j}\right] \left[\sum_{j=1}^{4} (X_{j} - \frac{1}{2}N_{j})\right]} \otimes$ (6)

Solving for σ gives

Ì

$$\hat{\sigma} \simeq \frac{1}{2\sqrt{3}} \frac{\sum_{j=1}^{n} \frac{(x_{j} - \hat{\phi} \sum_{j=1}^{n} x_{j})}{\sum_{j=1}^{n} (x_{j} - \frac{1}{2} x_{j})} ; \quad \sum_{j=1}^{n} (x_{j} - \frac{1}{2} x_{j}) \neq 0 \quad , \tag{7a}$$

but gives the indeterminate form 0/0 when $\sum (X_j - \frac{1}{2}N_j) = 0$. Noting that eq. (6) defines the sample mean of ϕ_j under the latter condition, we infer that

$$\hat{\sigma} \simeq \sqrt{\frac{\sum \phi_{1}^{2} N_{1}}{\sum N_{1}} - \left(\frac{\sum \phi_{1}^{N_{1}}}{\sum N_{1}}\right)^{2}} \quad ; \quad \sum (X_{j} - \frac{1}{2} N_{j}) = 0 \quad .$$
 (7b)

It follows from the definition of j that eqs. (6) and (7) apply only to data within the interval

$$\left|\frac{\phi_1 - \phi}{2\sqrt{3} \sigma}\right| < \frac{1}{2} \quad . \tag{8}$$

While the estimators $\hat{\phi}$ are expressed entirely in terms of the damage data, the data interval given by eq. (8) involves the unknowns ϕ and σ , and must be determined by trial and error. A satisfactory method for this has been developed, and is included in the routine data reduction procedure described below.

3.2 Data Reduction

Equations (6) through (8) are applied to each damage effect in turn via the calculator as follows. Fluences associated with the code number corresponding to a particular effect are sorted into a damaging, and the remaining fluences into a nondamaging category. Damaging fluences are then arranged and listed in order of ascending value, while the nondamaging fluences are listed in descending order. Data near the head of each list is examined for consistency by the operator and reclassified or discarded as required. Equations (6) and (7) are then applied to the revised lists. The j summations are initially taken over all data in the smallest interval which (a) includes the lowest damaging and highest nondamaging fluence, and (b) includes a damaging and nondamaging fluence as upper and lower limits, respectively. The interval is then extended as required to provide the minimum value of $\hat{\sigma}$, determined by applying eq. (7) to each new interval. This minimum $\hat{\sigma}$ and the $\hat{\phi}$ obtained by applying eq. (6) to the same interval are taken as the final results for the effect in question. In practice, it is found that $\hat{\phi}$ is rather intervalive to the data interval. However, $\hat{\sigma}$ depends more strongly on the number of data points used and their separation. Given adequate data the major contribution to $\hat{\sigma}$ usually comes from the variation of the damage threshold across the sample surface, with a relatively small contribution coming from the experimental uncertainty.

Repeated application of the algorithm gives an average threshold, together with its standard deviation, for each effect. The resulting thresholds for the target are presented in the form of a bar graph or damage profile, examples of which are presented below.

3.3 Reproducibility and Long-Term Calibration

The reproducibility of the threshold results can be demonstrated by repeated application to a sample with uniform damage characteristics over its surface, as indicated by relatively small standard deviations of the damage thresholds. A mirror produced by electrodeposition of Au on diamond-turned bulk Cu has this desirable property. The oxidation resistance is an added advantage, which makes this sample especially attractive as a standard for calibration maintenance. The ability to directly standardize damage thresholds is an invaluable asset in the long-term development of damage-resistant optical components.

Figure 3 presents the results of two independent multithreshold measurements on the standard gold sample. Figure 3(a) was obtained before, and figure 3(b) after replacing the output coupler on the laser over one month later. After correction for a 10% change in focal spot diameter, the thresholds for all effects listed except one agree within the combined standard deviations given. Statistically, approximately half the thresholds should agree this well when the effects are independent. It is clear that changing the output coupler had negligible effect on the calibration. Furthermore, we may conclude that the threshold algorithm gives consistent and reproducible results, the accuracy of which is conservatively represented by the standard deviations.

3.4 Examples

Multithreshold analysis has been applied to a variety of infrared mirror and window surfaces prepared by various techniques. Both coated and uncoated samples have been studied. The present section gives a few representative examples of results obtained.

The application of multithreshold analysis to relate damage mechanisms to surface characteristics of bare metal mirrors, particularly Cu, has been amply demonstrated [1]. Certain aspects of the Au mirror represented in figure 3 were also discussed. To complete this discussion it should be pointed out that the relatively high slip threshold indicated in figure 3 may be influenced by the difficulty in observing slip on this sample [1]. In fact, the lowest threshold is for work-function change, which is at ributed to evolution of water by the Au layer. This result is supported by a laser-induced diminution of oxygen as observed by Auger.

The value of multithreshold analysis in evaluating nominally equivalent mirror finishes is illustrated in figure 4, where we compare damage profiles of Ho mirrors polished by two different vendors. While mirror A exhibits higher thresholds for most types of damage, including melting, it is far more susceptible to pitting and associated plasma formation. The superior uniformity of mirror B is also evident in the smaller standard deviations.

As an example of multithreshold results from a window material we compare profiles for damage occurring on the entrance (front) and exit (back) surfaces of a polished NaCl blank (fig. 5). Only those sites where no simultaneous damage was observed on the front surface are represented in figure 5(b). All thresholds on the front are essentially the same, indicating breakdown as the only damage mechanism. Thresholds at the back surface are generally lower because of the constructive phase relationship between incident and reflected fields. Effects peculiar to the back surface are ripples, pits and fracture. Ripples result from the interference of incident and scattered radiation [6]. Present evidence shows that ripples occur only in the presence of a plasma. The pits may represent scattering sources for the ripples. The fact that pits occur only on the back surface suggest that they result from bulk, rather than from surface inhomogenetties. Scrubbing associated with the plasma, which was observed in mirrors [1], has also been observed on this sample.

A damage profile from an enhanced-reflection coating on polished bulk Cu is shown in figure 6. The thresholds are well below those for bare (v., Pitting que to coatin, defects is the dominant failure mode. Almost identical damage profiles were obtained when the same coatin; design was applied to Mo and to ULE glass.

Figure 7 compares damage thresholds from magS3 in bulk form, and as a costing [7] on the NaCl. In the bulk material the coincidence of thresholds for surface pitting and bulk damage suggest that these result from the same mechanism which, surprisingly, is active below the threshold for pitting in the coating. Also, pitting in the coating tends to associate with a plasma, which is not true in the bulk material:

4. Summary

An efficient and reliable method has been developed for simultaneously measuring the thresholds and standard deviations for up to eight laser-damage-related effects on a single sample. An algorithm based on the maximum-likelihood principle has been derived for computing results directly from the experimental data. Reproducibility has been demonstrated by repeated measurements on a standard Au sample. The use of this sample to maintain long-term calibration was described. Examples of multi-threshold results on representative optical components of each type have been given and the principal weaknesses of these components identified. The comparative analysis of such results from well characterized samples prepared from different materials and by different rechniques yields the relationship between damage thresholds and material characteristics. These comparisons can also provide a better understanding of laser-damage mechanisms.

5. Acknowledgments

The authors are indebted to G. J. Sorenson for programming the plot routine for the damage profiles.

6. References

[1] Porteus, J. O., Fountain, C. V., Jordigan, J. L., Faith, W. N. and Bennett, K. P., this conference.

- [2] Porteus, J. O., Soilesu, M. J. and Bennett, H. E., in Laser Induced Desnage in Optical Materials: 1975, A. J. Glass and A. H. Guenther, eds. (NBS Spec., Publ., 435), p. 207.
- [3] Bass, M. and Leung, K. M., IEEE J. Quantum Electron, OE-12, 32 (1976).
- [4] For n-on-1 damage the situation is obviously equivalent if nondamaging pulses leave an equivalent damage probability at each site.
- (5) Mood, A. M., Introduction to the Theory of Statistics (McGraw-rill, New York, 1950), Ch. 8.

- [6] Temple, P. A. and Soileau, M. J., in Laser Induced Damage in Optical Materials: 1976, A. J. Glass and A. H. Guenther, eds. (NBS Spec. Publ. 462), p. 371.
- [7] Donovan, T. M., Baer, A. D., Dancy, J. H. and Porteus, J. O., this conference.

features.

Figure 1. Micrographs of visible damage on polished bulk Cu at a peak fluence of 68.3 J/cm². In Nomarski, slip bands appear outside the crater at the 5 o'clock position, while intergranular slip is responsible for prominent crack-like

7. Figures

CRATER, SLIP, PITS

BULK Cu, OPTICAL POLISH



NOMARSKI



DARK FIELD

200 μm




Figure 2. Gaussian spatial profile of focussed laser pulse, showing 1/e2 width and peak energy density (fluence) at which thresholds are determined.




Figure 3(a). Damage profile of standard gold sample, measured for calibration with the original laser output coupler. Thresholds are indicated by the shaded bars. Standard deviations (+ or -) are indicated by the semishaded boxes at the ends of the bars.




Figure 3(b). Damage profile to be compared with figure 3(a), measured for calibration with new laser output coupler.

ì




Figure 4(a). Damage profile of polished bulk Mo from vendor A.




Figure 4(b). Damage profile of polished bulk Mo from vendor B.





Figure 5(a). Front surface damage profile of a NaCl blank, 6.4-mm thick, polished or both surfaces.



The state of the s

Figure 5(b). Profile of damage occurring only on the back surface of the same blank. The laser beam was focussed on the front surface.

BULK Cu, OPTICAL POLISH, E-R COATED




Figure 6. Damage profile of a $10.6-\mu m$ enhanced reflection coating on bulk Cu. Coating consists of alternating layers of Ge and ZnS on a thin Ag layer.

As283 COATING ON NaCI, FRONT SURFACE




Figure 7(a). Damage profile of an As_2S_3 coating on the front surface of NaCl.




Figure 7(b). Damage profile of polished bulk As₂S₃,